ഉത്തരം

(എ) 1985–86–ലെ വെള്ളപ്പൊക്കദുരിതാശ്വാസത്തിൽ ഉൾപ്പെടുത്തിയ ഇറിഗേഷൻ പണികൾക്കുവേണ്ടി 1,030 ലക്ഷം രൂപ ലഭിച്ചു.

(ബി) മൈനർ ഇറിഗേഷൻ–422.50 ലക്ഷം രൂപ; ഇറിഗേഷൻ–607.50 ലക്ഷം രൂപ.

(സി) തിരുവനന്തപുരം ജില്ലയിൽ ഇറിഗേഷൻ ഡിവിഷന്റെ കീഴിലുള്ള പണികൾക്കായി 46.30 ലക്ഷം രൂപയും, മൈനർ ഇറിഗേഷൻ ഡിവിഷന്റെ കീഴിലുള്ള പണികൾക്കായി 23.50 ലക്ഷം രൂപയും നൽകിയിരുന്നു. ഇതോടൊപ്പം ചേർത്തിരിക്കുന്ന ലിസ്റ്റിൽ ഉൾപ്പെടുത്തിയിട്ടുള്ള പണികൾക്കാണ് മുകളിൽ കാണിച്ചിരിക്കുന്ന തുക അനുവദിച്ചിട്ടുള്ളത്.†

കിഴക്കെ കല്ലട പഞ്ചായത്തിലെ മിനി കനാലിന്റെ പണി

422 [459] ശ്രീ. തോപ്പിൽ രവി: താഴെ കാണുന്ന ചോദ്യത്തിന് നിയമവും ജലസേചനവും വകുപ്പു മന്ത്രി സദയം മറുപടി നൽകുമോ:

കിഴക്കെ കല്ലട പഞ്ചായത്തിലെ ഉപ്പൂട് ലിഫ്റ്റ് ഇറിഗേഷൻ പദ്ധതിയുടെ ഭാഗമായി നിർമ്മിക്കുന്ന മിനി കനാലിന്റെ പണികൾ എത്രത്തോളം പുരോഗമിച്ചു എന്നു വ്യക്തമാക്കാമോ?

ഉത്തരം

പണി പൂർത്തിയായി വരുന്നു.

ഓണമ്പലം കട്ടിന്റെ പണി

423 [460] ശ്രീ. തോപ്പിൽ രവി: താഴെ കാണുന്ന ചോദ്യങ്ങൾക്ക് നിയമവും ജലസേചനവും വകുപ്പു മന്ത്രി സദയം മറുപടി നൽകുമോ:

(എ) ചിറ്റുമല ഏലായിലെ അധികജലം അഷ്ടമുടിക്കായലിലേക്കു ഒഴുക്കിക്കളയാൻ ഉദ്ദേശിച്ചുകൊണ്ടുള്ള ഓണമ്പലം കട്ടിന്റെ പണികൾ വർഷങ്ങളായി മുടങ്ങിക്കിടക്കുകയാണെന്ന കാര്യം ഗവൺമെന്റിന്റെ ശ്രദ്ധയിൽപ്പെട്ടിട്ടുണ്ടോ;

(ബി) ഈ പണികൾ പുനരാരംഭിക്കുവാൻ സ്വീകരിച്ചിട്ടുള്ള നടപടികൾ വിശദീകരിക്കാമോ?

ഉത്തരം

(എ) ഉണ്ട്.

(ബി) ഓണമ്പലം കട്ടിന്റെ പണി 1976–77-ൽ ഏറ്റെടുത്തു നടത്തുവാൻ അനുവദിച്ച കരാറുകാരൻ വളരെ കുറച്ചു പണികൾ മാത്രം നടത്തിയശേഷം ഏകപക്ഷീയമായി പണി നിർത്തി. അതിനാൽ ആ കരാർ റദ്ദാക്കി. തുടർന്നു രണ്ടു പ്രാവശ്യം ടെണ്ടർ ക്ഷണിച്ചെങ്കിലും പ്രതികരണമുണ്ടായില്ല. അതിനെത്തുടർന്നു കാട്ടേഷൻ മുഖേന പണികൾ നടത്തുവാൻ ഏൽപ്പിച്ച കരാറുകാരിയും പണി തുടരാൻ കാര്യമായ ശ്രമമൊന്നും കാണിക്കാത്തതുകൊണ്ട് ആ കരാറും റദ്ദാക്കി. പ്രസ്തുത പണിയുടെ

† അനുബന്ധം I

LIBRARY ARCHIVES Kerala Legislative Assembly

ബാക്കി ഭാഗം കരാർ വ്യവസ്ഥയിൽ ചെയ്യുന്നതിനു G.O. (Rt) 42/85/W and P dated 15-1-1985 പ്രകാരം കേരളാ സ്റ്റേറ്റ് കൺസ്ട്രക്ഷൻ കോർപ്പറേഷനെ ഏൽപ്പിച്ചിട്ടുണ്ട്. ഈ വകയ്ക്കു 5 ലക്ഷം രൂപ കൂടി പലിശയില്ലാ അഡ്വാൻസായി കോർപ്പറേഷനു അനുവദിച്ചുകൊടുത്തിട്ടുണ്ട്. എന്നാൽ മുൻ കരാറുകാരി, തന്റെ ചെയ്ത പണിയുടെ അളവിനെ സംബന്ധിച്ചു തീരുമാനങ്ങൾക്കായി കോടതിയെ സമീപിച്ചിട്ടുണ്ട്. കൺസ്ട്രക്ഷൻ കോർപ്പറേഷനെ കൊണ്ട് പണി തുടങ്ങുന്നതിനാവശ്യമായ അടിയന്തിര നടപടികളും സ്വീകരിച്ചിട്ടുണ്ട്.

പാലാട് പടന്ന തോട്ടിൽ കെട്ടിക്കിടക്കുന്ന മലിന ജലം

424 [461] ശ്രീ. പി. ഭാസ്കരൻ: താഴെ കാണുന്ന ചോദ്യങ്ങൾക്ക് നിയമവും ജലസേചനവും വകുപ്പു മന്ത്രി സദയം മറുപടി നൽകുമോ:

(എ) കണ്ണൂർ മുനിസിപ്പാലിറ്റിയിൽനിന്നും ഒഴുക്കിപ്പോകുന്ന അഴുക്ക് ജലം പാലാട് പടന്ന തോട്ടിൽ കെട്ടിക്കിടക്കുന്നതുമൂലം ഉണ്ടാകുന്ന ബുദ്ധിമുട്ടുകളെക്കുറിച്ച് എന്തെങ്കിലും പരാതി കിട്ടിയിട്ടുണ്ടോ;

(ബി) ഇതിന് പരിഹാരനടപടി സ്വീകരിക്കുമോ?

ഉത്തരം

(എ) ഉണ്ട്.

(ബി) പരിഹാരനടപടി എന്ന നിലയിൽ ഒരു സീവേജ് ഫിൽറ്റർ നിർമ്മിച്ച് അഴുക്ക് ജലം സംസ്കരിച്ച് സമീപത്തുള്ള തോട്ടിലേയ്ക്ക് വിടുവാനുള്ള സംവിധാനം ഉണ്ടായിരുന്നു. ഈ സംവിധാനത്തോട് വദനപ്പാലം പരിസരത്തുള്ള ജനങ്ങൾ എതിർപ്പ് പ്രകടിപ്പിച്ചിരുന്നു. മുനിസിപ്പാലിറ്റിയിൽനിന്നും ഉള്ള മലിനജലം പള്ളിക്കുന്ന് പഞ്ചായത്തിൽപ്പെട്ട വദനപ്പാലത്ത് ഒഴുകി എത്തരുതെന്നാണ് അവരുടെ നിലപാട്. ഭൂപ്രകൃതി അനുസരിച്ച് മുനിസിപ്പാലിറ്റിയ്ക്ക് തൊട്ട് കിടക്കുന്ന താഴ്ന്ന പ്രദേശം എന്ന നിലയ്ക്ക് അഴുക്കു വെള്ളത്തിന്റെ ഒഴുക്ക് ഒഴിവാക്കുക പ്രയാസമാണ്. നിലവിലിരിക്കുന്ന ഫിൽറ്ററിലേയ്ക്കുള്ള പമ്പിംഗ് സംവിധാനത്തിന് നാട്ടുകാർ നിരന്തരം നാശനഷ്ടങ്ങൾ വരുത്തിക്കൊണ്ടിരിക്കുന്ന സാഹചര്യത്തിൽ ഇതിന്റെ പ്രവർത്തനം നിർത്തിവച്ചിരിക്കുകയാണ്. ഇപ്പോൾ ജില്ലാ കലക്ടറും മറ്റും ഇടപെട്ട് ഒരു ആക്ഷൻ കമ്മിറ്റി സംഘടിപ്പിക്കുകയും കമ്മിറ്റി വേണ്ട നടപടികൾ കൈക്കൊണ്ടു വരികയും ചെയ്യുന്നു.

കവടിയാർ പണ്ഡിറ്റ് കോളനി ഹൗസിംഗ് സ്കീമിനോടനുബന്ധിച്ചുള്ള ഡ്രെയിനേജ് സ്കീം

425 [462] ശ്രീ. പി.സി. ജോർജ്ജ്: താഴെ കാണുന്ന ചോദ്യങ്ങൾക്ക് നിയമവും ജലസേചനവും വകുപ്പു മന്ത്രി സദയം മറുപടി നൽകുമോ:

(എ) തിരുവനന്തപുരം കവടിയാർ ഭാഗത്തുള്ള പണ്ഡിറ്റ് കോളനി ഹൗസിംഗ് സ്കീമിനോടനുബന്ധിച്ചുള്ള തിരുവനന്തപുരം ഡ്രെയിനേജ് സ്കീം ''ഡി'' ബ്ലോക്കിന്റെ പണികൾ ഇതുവരെ തുടങ്ങാതിരിക്കാനുള്ള കാരണമെന്താണെന്ന് വ്യക്തമാക്കാമോ;

LIBRARY ARCHIVES Kerala Legislative Assembly

അനുബന്ധം—I

[നക്ഷത്രചിഹ്നമിടാത്ത ചോദ്യം നമ്പർ 421 (458) കാണുക]

A. S. E. WORK

IRRIGATION DIVISION—TRIVANDRUM

Flood damages 1985—Repairs and Reconstruction of Sea Walls

Sl.No.	*Name of work*	*Estimate Amount (Rs. in lakhs)*
1	Urgent protective works at Punathakara to protect houses from sea erosion between BLS.206 and 210.	0.65
2	Do. do. BLS. 213 & 215	0.65
3	Do. do. ,, 215 & 216	0.65
4	Do. do. ,, 216 & 217 (near Ch. stone 5983)	0.65
5	Do. do. ,, 217 & 219	0.65
6	Do. do. ,, 219 & 220	0.65
7	Do. do. ,, 220 & 222	0.65
8	Do. do. ,, 222 & 224	0.65
9	Do. to protect the Kovalam canal due to sea erosion near BLS. 209	0.65
10	Do. to protect the Mosque at Kovalam adjacent to I.T. B.C. Bathing chat	0.65
11	Urgent protective works at Punathakara constructing core wall for protecting the eroded sea shore between BLS. 202 & 204.	3.10
12	Do. do. BLS. 204 & 206	3.50
13	F. D. works forming protective rubble round on the south of Muthalapozhy at Perumathura.	0.92
14	F. D. A.S.E. works reforming the sea wall between C.P. 5734 and 5735 at Thazhampally for a length of 60 m.	1.04
15	F.D. A.S.E. work reforming sea wall for 60 m. between C. P. 5722 at Poonthura.	1.11

LIBRARY ARCHIVES Kerala Legislative Assembly

Sl.No.	*Name of work*	*Estimate Amount (Rs. in lakhs)*
16	F.D. A.S.E. work rectification of damages to the existing sea wall at Thazhampally between C.P. 5739 & 5740.	0.85
17	Sea erosion urgent protective work near C.P. 5713 at Anjengo.	0.19
18	Sea erosion urgent protective work near C.O. 5718 at Poonthura.	0.19
19	Sea erosion urgent protective works on the north of C.P. 5723 at Poonthura.	0.42
20	Sea erosion at Poonthura urgent protective work on the south of C.O. 5721 at Poonthura.	0.49
21	Sea erosion urgent protective works on the north of C.P. 5713 near Vadikkakom at Angengo.	0.18
22	Sea erosion at Poonthura urgent protective works on the north of C.O. 5722 at Poonthura.	0.43
23	Sea erosion urgent protective works south of C.P. 5723 Poonthura.	0.48
24	Sea erosion at Poonthura urgent protective works on the rear side of Poonthura church to protect the flag post of the Poonthura church southern side.	0.25
25	Sea erosion at Poonthura urgent protective works on the northern side of flag post of the church.	0.25
26	Sea erosion on the sides of Rocket Launching Station at Thumba urgent protective works on the road side of Thaivilakom area.	0.23
27	Sea erosion at Veli urgent protective works on the northern side of Veli Church.	0.24
28	Sea erosion at Vettukadu urgent protective works on the near side of Vettukaduchurch.	0.24

FLOOD DAMAGES 1985—ADDITIONAL LIST OF WORKS

Repairs & Reconstruction of Sea Walls

TRIVANDRUM DISTRICT

Sl. No.	Name of work	Estimate amount Rs. in lakhs
29	Urgent protective works at Pannathakara to protect houses from sea erosion between BLS. 224 & 226.	0.65
30	Do. do. near BLS. 212.	65
31	F.D. work (ASE) rectification of damages to the existing sea wall at Thazhanpally between C.P. 5731 & 5732.	1.35
	Total	2.65

LIBRARY ARCHIVES Kerala Legislative Assembly

F. C. WORKS

IRRIGATION DIVISION—TRIVANDRUM

Flood Damages 1985 — Repairs to river banks and canals

Sl.No.	*Name of work*	*Estimate Amount (Rs. in lakhs)*
1	F.D. work in Karamana river L.B. of Manamel to Kamachal thodu at Thiruvallam Panchayat	0.83
2	F. D. work—Protecting the L.B. of Karamana river opposite of Kulasekharam temple at Parayar.	0.80
3	F.D. R.B. of Neyyar dam d/s. of Amaravila bridge.	0.80
4	Do. opposite of Kulasekharam temple 2nd reach	0.91
5	Do. R. B. of Karamana river d/s. of Thrikkannapuram ferry	0.51
6	Do. R. B. of Karamana river at Sy. No. 2468/146-1 Randamada Village, Vettom Malamughal.	0.55
7	Do. Protecting the L/B. of Killiyar Sy. No. 1346/13 of Randamada Village near Thozhuvancode.	1.09
8	Do. Protecting the R.D. of Karamana river at Kulasekharapuram D/S. of Kulasekharam temple.	0.76
9	Do. R. B. of Karamana river d/s. of Irumbil Kadavu.	1.43
10	Do. The R. B. of Karamana river in Thrikkannapuram 750 m. u/s. of Thrikkannapuram ferry.	0.32
11	Do. R. B. of Karamana river at Kummiyil Kadavu in Aruvikara Panchayat.	0.46
12	Do. L. B. of Karamana river Sy. No. 3608 in Anchamada Village	0.68
13	Do. R. B. of Killiyar in Sy. No. 1290 and 1298 of Randamada village at 300 m. u/s. of Pangode bridge.	0.49
14	Do. Protecting works on the sides of Amazyizhanchan thodu d/s. of Ulloor bridge near Yamuna Garden.	1.45
15	Do. Eroded L/B. of Vamanapuram river at Thazhamathottam near Ayilam in Mudhakal Panchayat.	0.55
16	Do. Sides of Velikayal near Veli Youth Hostel and boat club at Veli.	1.70
		13.33

LIBRARY ARCHIVES Kerala Legislative Assembly

Sl. No.	Name of work	Estimate Amount (Rs. in lakhs)
	TRIVANDRUM DISTRICT	
17	F.D. work protecting works on the sides of Amayizhanchan thodut Perumpalam in Sreekariyam Panchayat.	0.50
18	Do. R.B. of Vamanapuram river at Koyyarakadavu in Kadakkavoor Panchayat	1.00
	Total	1.50
19	Protecting the eroded banks of leading chal of Neeramankara tank near N.S.S. School.	1.15
20	F.D.—Improvements to Melpayoorkulam and leading chal in Nalanchira in Chettivilakom Panchayat	1.95
21	Protection works to the side bunds of Vamanapuram in Sy. No. 713/6	1.00

LIBRARY ARCHIVES Kerala Legislative Assembly

MINOR IRRIGATION WORKS

Flood damage 1985—Repairs to M. I. Works

Sl. No.	*Name of work*	*Estimates Amount Rs. in lakhs*
	MINOR IRRIGATION SUB DIVISION—TRIVANDRUM	
1	F.D. Improvements to the leadingal of Anathazhachira down stream of Pallippuram Pothencode road upto Vettu road in Andoorkonam Panchayat	1.70
2	F.D. Providing protective works to Vadarukoman thodu in Nedumangad Municipality	1.60
	MINOR IRRIGATION SUB DIVISION—ATTINGAL	
3	F.D. Closing breaches and protective works to the thodu from Kurininada to Mahadevancoil temple in Kuzhuvalam Panchayat	0.62
4	Do. to Cherukottikonam ela thodu in Nallanad Panchayat	0.61
5	R.D. to Muthana ela in Chemmaruthy Panchayat	0.62
6	R.D. to Noolayil Moongod thodu in Manampoor Panchayat	1.46
	MINOR IRRIGATION SUB DIVISION—NEYYATTINKARA	
7	F.D. Rectification of damages to Kumbil thodu—Improvements to Melamathoor Kuthukuzhi in Kuttichal Panchayat	1.27
8	Do. to Nadavoorkulam to Karode Panchayat	0.99
9	Do. Rectification of damages to Karathodu in Pandarakari Padasekharam	1.45
10	Improvements including protection wall to Kunnathu Chirakulam in Chettivilakom Panchayat	1.50

LIBRARY ARCHIVES Kerala Legislative Assembly